

SEP 9

In reply refer to: PA/GA-225

CM 103, REVISION C, STOWAGE LIST CHANGE NOTICE (SLCN)

SLCN NO. 2C

September 9, 1968

LOC	070-33
SIGNATOR	MSC
SUBJECT	
PGM	CSM
T	R
#	

FOR INFORMATION, CONTACT ASPO, GFE OFFICE  
PF3/J. W. Thompson, HU 3-5411


COMAT KEY:

- A - Approved
- P - COMAT submitted, approval pending
- O - Open, design incomplete
- M - Metal

INDEXING DATA	OPR
DATE	09-09-68
	MSC

NASA MSC Archives

Number  
Date



NATIONAL AERONAUTICS AND SPACE ADMINISTRATION  
MANNED SPACECRAFT CENTER  
HOUSTON, TEXAS 77058

IN REPLY REFER TO: PA/GA-225  
Contract NAS 9-150

SEP 23 1968

Mr. Milton I. Drucker  
Director, Apollo CSM Program Contracts  
Space Division  
North American Rockwell Corporation  
Downey, California 90241

Dear Mr. Drucker:

In accordance with agreements reached at the NASA/NR technical status review meeting, June 20, 1968, recent changes to the CM 103 stowage configuration, which have been individually approved by the NASA/MSC CCP/CCB (Configuration Control Panel/Configuration Control Board), are summarized in the SLCN (Stowage List Change Notice) number 2C to revision C of the CM 103 stowage list, enclosed. The contractor is requested to modify exhibit G and affected engineering documentation and specifications to incorporate these changes. In the event a modification of the CSM vehicle is required for compliance, NASA/MSC should be notified.

Sincerely yours,

A handwritten signature in cursive script, which appears to read "Jack Fuller", is written over the typed name.

Jack Fuller  
Contracting Officer  
Spacecraft Contract Section

Enclosure

cc:  
NR-Houston

DATE		STOWAGE LIST CHANGE NOTICE					Page <u>1</u>	
September 9, 1968		(This change will be incorporated in the next Stowage List Rev.)					of <u>3</u>	
MODULE			SECTION		REVISION		SLCN NUMBER	
CM 103			I - STOWED OPERATIONAL GFE		C		2C	
ITEM	NOMENCLATURE	PART NUMBER	UNIT WT (LB)	QTY PER S/C	STOWAGE LOCATION	COMAT	REASON FOR CHANGE	LIST EFFECT
110	Ring Sight				A8	A	SICN 1C in error, not stowed on 70MM camera. Fit not affected.	
134A	Accessory Bag	SEB 13100114-701				A	Part number change from SEB 40100182-701. Reason: Information at original release in error. Ref. CCBD 8C1113 approved 8-9-68. RECP 8E275. Fit not affected.	
167	Lightweight Headset	C-0072-3 or SLB16100795-303				A	Added MSC part number. Fit not affected.	
168	Universal Ear Tube	SLB16100795-322	TBD	3	Stow 1 each in each inflight coverall jacket pocket in volume A8.	A	Addition of item. Original release error. Fit is affected.	

DATE		STOWAGE LIST CHANGE NOTICE					Page <u>2</u>	
September 9, 1968		(This change will be incorporated in the next Stowage List Rev.)					of <u>3</u>	
MODULE			SECTION		REVISION		SLCN NUMBER	
CM 103			III - CREW APPAREL		C		2C	
ITEM	NOMENCLATURE	PART NUMBER	UNIT WT (LB)	QTY PER S/C	STOWAGE LOCATION	COMAT	REASON FOR CHANGE	LIST EFFECT
309	Lanyard, Scissors	SDB42100118 -701	TBD	3	On PGA		Item deleted. Reason: part of scissors. Fit not affected.	

DATE		STOWAGE LIST CHANGE NOTICE					Page <u>3</u>	
September 9, 1968		(This change will be incorporated in the next Stowage List Rev.)					of <u>3</u>	
MODULE			SECTION		REVISION		SLCN NUMBER	
CM 103			IV - STOWED OPERATIONAL CFE		C		2C	
ITEM	NOMENCLATURE	PART NUMBER	UNIT WT (LB)	QTY PER S/C	STOWAGE LOCATION	COMAT	REASON FOR CHANGE	LIST EFFECT
406	End Wrench Tool F	V36-601415					Part number change from V36-601417. Reason: typographical error.	
	Tool "L"	TBD	TBD	1	A1		Addition of item. Reason: MCR 7806.	
407A	Container, R10 Fwd	V36-601420					Deletion of dash number. Reason: SLCN No. 1C in error.	
458	Container, Snag Line	V36-787019 -11					Part number change to -11 Reason: MCR-A6791, E.O. - M707021.	